



CARFAX® Vehicle History Report™

US \$39.99

An independent company established in 1986

Vehicle Information:

2010 TOYOTA TUNDRA DOUBLE CAB SR5

VIN: 5TFUW5F16AX116311

4 DOOR EXTENDED CAB PICKUP

5.7L V8 F DOHC 32V

FLEX FUEL

REAR WHEEL DRIVE W/ 4X4

[Standard Equipment](#) | [Safety Options](#)



No accidents reported to CARFAX



No other damage reported to CARFAX



CARFAX 1-Owner vehicle



At least 1 open recall



7 Service history records



144,023 Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 3/12/18 at 6:38:56 AM (EDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Year purchased

2010

Type of owner

Corporate

Estimated length of ownership

2 yrs. 11 mo.

Owned in the following states/provinces

Texas

Estimated miles driven per year

48,391/yr

Last reported odometer reading

144,023



Title History

CARFAX guarantees the information in this section

Owner 1

[Salvage](#) | [Junk](#) | [Rebuilt](#) | [Fire](#) | [Flood](#) | [Hail](#) | [Lemon](#)

Guaranteed
No Problem

[Not Actual Mileage](#) | [Exceeds Mechanical Limits](#)

Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. [Register](#) | [View Terms](#)



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No Issues

| | |
|--|------------------------|
| No total loss reported to CARFAX. | Reported |
| Structural Damage | No Issues |
| No structural damage reported to CARFAX. | Reported |
| Airbag Deployment | No Issues |
| No airbag deployment reported to CARFAX. | Reported |
| Odometer Check | No Issues |
| No indication of an odometer rollback. | Indicated |
| Accident / Damage | No Issues |
| No accidents or damage reported to CARFAX. | Reported |
| Manufacturer Recall | Recall Reported |
| At least 1 manufacturer recall requires service. Locate an authorized Toyota dealer near you to schedule an appointment. | |

CARFAX Detailed History Glossary

Owner 1
Purchased: 2010
Type: Corporate
Where: Texas
Est. miles/year: 48,391/yr
Est. length owned: 1/19/10 - 1/9/13 (2 yrs. 11 mo.)

| Date: | Mileage: | Source: | Comments: |
|------------|----------|--|---|
| 10/19/2009 | | NICB | Vehicle manufactured and shipped to Texas |
| 10/24/2009 | | Red McCombs Toyota San Antonio, TX 210-530-3000 redmccombstoyota.com | Vehicle offered for sale |
| 10/29/2009 | 2 | Red McCombs Toyota San Antonio, TX 210-530-3000 redmccombstoyota.com | Pre-delivery inspection completed VIN glass etching vin etched Window tint installed |
| 12/23/2009 | 13 | Red McCombs Toyota San Antonio, TX 210-530-3000 redmccombstoyota.com | Vehicle sold |
| 01/19/2010 | | Texas Motor Vehicle Dept. San Antonio, TX Title #01535440183150741 | Title issued or updated First owner reported Titled or registered as corporate vehicle |
| 08/14/2010 | 32,532 | Lithia Toyota of Odessa Odessa, TX 432-498-0400 odessatoyota.com | Maintenance inspection completed |
| 12/01/2010 | | Texas Motor Vehicle Dept. San Antonio, TX Title #01535440183150741 | Registration issued or renewed Passed safety inspection |
| 03/04/2011 | | Toyota Motor Sales, USA, Inc. | Manufacturer Safety recall issued NHTSA #11V148 Recall #B0B SAFETY (NON-COMPLIANCE) RECALL B0B - CERTAIN 2008 THROUGH 2011 MODEL YEAR LAND CRUISER, SEQUOIA, TACOMA AND TUNDRA VEHICLES EQUIPPED WITH TOYOTA-RECOMMENDED LIGHT TRUCK TIRES AND TRD ACCESSORY WHEEL Status: Remedy Available |

Locate an authorized [Toyota dealer](#) near you to schedule an appointment

Description: Toyota is recalling certain Model Year 2008 through 2011 FJ Cruiser, Land Cruiser, Tacoma, Sequoia and Tundra vehicles for failing to comply with the requirements of Federal Motor Vehicle Safety Standard no. 138, Tire pressure monitoring system (tpms). when factory-installed wheels and tires were replaced with Toyota authorized accessory wheels and It tires prior to first sale, the tire pressure monitoring systems were not re-calibrated correctly and therefore do not start illuminating the low tire pressure warning telltale at the required minimum activation pressure.

Failure to warn of tire deflations is a non-compliance with FMVSS 138 and could lead to tire failure increasing the risk of a crash.

Remedy: For the Land Cruiser, Sequoia, Tacoma and Tundra vehicles, the dealer will re-calibrate the tire pressure monitoring system (TPMS) on affected vehicles and install an updated tire and loading information label at no charge. For the FJ Cruiser vehicles, the TPMS cannot be reset so the electronic control unit (ECU) for the TPMS will be replaced. If an owner is not certain whether his or her vehicle is equipped with these accessories, please contact any Toyota dealer for an inspection at no charge. The safety recall began on March 31, 2011. Owners may contact Toyota at 1-800-331-4331.

| | | | |
|------------|---------|--|--|
| 12/01/2011 | | Texas Motor Vehicle Dept. San Antonio, TX Title #01535440183150741 | Registration issued or renewed Passed safety inspection |
| 06/14/2012 | 124,780 | Lithia Toyota of Odessa Odessa, TX 432-498-0400 odessatoyota.com | Electrical system checked |
| 07/24/2012 | 125,896 | Lithia Toyota of Odessa Odessa, TX 432-498-0400 odessatoyota.com | Maintenance inspection completed Emission system checked Engine serviced Tire condition and pressure checked |
| 12/01/2012 | | Texas Motor Vehicle Dept. San Antonio, TX Title #01535440183150741 | Registration issued or renewed Passed safety inspection |
| 01/07/2013 | 143,968 | Toyota of Midland Midland, TX 432-520-4114 toyotaofmidland.com | Pre-delivery inspection completed Engine checked Engine/powertrain computer/module checked Oil and filter changed |
| 01/09/2013 | 143,982 | Toyota of Midland Midland, TX 432-520-4114 toyotaofmidland.com | Vehicle offered for sale |
| 01/28/2013 | 143,999 | Toyota of Midland Midland, TX 432-520-4114 toyotaofmidland.com | Vehicle serviced |
| 02/18/2013 | 144,023 | Toyota of Midland Midland, TX 432-520-4114 toyotaofmidland.com | Vehicle serviced |
| 03/04/2013 | | Toyota of Midland Midland, TX 432-520-4114 | Vehicle sold |

04/19/2013 Vehicle Exporter Vehicle exported from

Newark, NJ
and imported to
Lithuania

03/31/2014 Toyota Motor Sales, USA, Inc. Manufacturer Service Campaign issued Campaign #BST SPECIAL SERVICE CAMPAIGN (SSC) BST MULTIPLE MODEL AND MODEL YEARS SMART STOP TECHNOLOGY
Status: Remedy Available

Locate an authorized [Toyota dealer](#) near you to schedule an appointment

[Learn more about this campaign](#)

Description: In our continuing effort to ensure the best in customer satisfaction, Toyota has converted Limited Service Campaign (LSC) BST into Special Service Campaign (SSC) BST with no expiration date.

Remedy: Toyota will install Smart Stop Technology on the involved model and model year vehicles. This feature will cut engine power in case of simultaneous application of both the accelerator and brake pedals at certain speeds and in certain driving conditions.

09/17/2015 Toyota Motor Sales, USA, Inc. Manufacturer Safety recall issued NHTSA #15V689 Recall #C0M SAFETY RECALL C0M REMEDY NOTICE - MULTIPLE MODELS AND MODEL YEARS - POWER WINDOW MASTER SWITCH (PWMS)
Status: Remedy Available

Locate an authorized [Toyota dealer](#) near you to schedule an appointment

[Learn more about this recall](#)

Description: The Power Window Master Switch in the involved vehicles may have been manufactured with insufficient lubricant grease.

If sufficient grease is not applied, under certain conditions the switch may develop a short circuit that can cause the switch assembly to overheat and melt. A melting switch can produce smoke and potentially lead to a fire.

Remedy: Toyota is currently preparing the remedy for this condition. Once remedy preparations are complete, Toyota will send an owner notification letter by first class mail to owners of vehicles covered by this Safety Recall. Additional details on the remedy will be provided in future communications.



Hmm, we haven't received any information on this car since September 2015. Before you buy, ask the seller for recent service or repair records.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Toyota Recall / Service Campaign

Toyota Motor Sales, USA, Inc. provides CARFAX with recall and service campaign information for vehicles originally marketed or sold in the United States of America, its territories, and Mexico. Only open safety or emissions recalls and service campaigns where the remedy has not been completed, will be listed. While Toyota provides data updates to CARFAX on a regular basis, this report may not include very recent activity. For the most current information on recall and campaign activity for any Toyota vehicle, you must go to <http://toyota.com/recall>.

Follow Us:  facebook.com/CARFAX  [@CarfaxReports](https://twitter.com/CarfaxReports)  [CARFAX on Google+](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2018 CARFAX, Inc., a unit of IHS Inc. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

3/12/18 6:38:56 AM (EDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 TOYOTA TUNDRA vehicle (VIN: 5TFUW5F16AX116311), which is based on information supplied to CARFAX and available as of 3/12/18 at 6:38 AM (EDT).

Customer Signature

Date

Dealer Signature

Date